

OVERHEATING on the OLYMPUS FILM CAMERAS - AZ 200/210/220 Panorama/230 Zoom or AF-1 Twin

For customers using Olympus Film cameras; AZ 200/210/220 Panorama/230 Zoom or AF-1 Twin. [OLYMPUS IMAGING EUROPA](#) would like to advise that the aforementioned models manufactured during 1988 and 1994, in rare cases have been known to generate heat and smoke when the power is turned on. The camera body may also blister the spot area of the outer cover.

We wish to emphasize that the camera body is made of incombustible materials, which means there will be no danger of burning.

[OLYMPUS IMAGING EUROPA](#) wishes to advise [its customers](#) owning these models that we will provide free inspection and prevention measures on these cameras. If you are using these models, please send your camera into our service station, details on the repair Services homepage. (Transit cost will be incurred by the customer). Unfortunately if your camera has passed its warranty, we will be unable to offer this service.

Models this may apply to:

- AZ 200 Zoom: manufactured from 1989 to 1992
- AZ 210 Zoom: manufactured from 1990 to 1993
- AZ 220 Panorama Zoom: manufactured from 1991 to 1993
- AZ 230 Zoom: manufactured from 1991 to 1994
- AF-1 Twin: manufactured from 1988 to 1992

Contact to us:

[Please contact our Service Station mentioned on the repair services page.](#)

Please Note:

The personal information gathered from customers; name and address, phone number, will not be used for the purposes other than receipt of the goods, inspection, and return shipment.

[OLYMPUS IMAGING EUROPA](#)